

# PROCESS SPECIFICATION

PROCESS SPECIFICATION NUMBER: ERA-1024
BO-105 C 20 R ENGINE INSTALLATION
FABRICATION OF THE ENGINE AIR INLET

PREPARED BY:

John E. Stanley MESH COMPOSITES INC. DATE: 1/18/88

APPROVALS

JITY CONTROL	ENGINEERING	
ofu E Sto	- Last Care	MESH
luphy	J. A Source J.	. ERA
	of Elto	The Elst South English The



**GULF COAST DIVISION** LAKE CHARLES, LOUISIANA

# PROCESS SPECIFICATION

Scope:

This specification outlines the requirements

for fabricating the engine air inlet for the

C 20 R engine for the BO-105

Conformation:

This specification does not conform to any

existing government specification.

Subcontractors: MESH COMPOSITES INC. of Lake Charles, Louisiana,

or its subcontractor shall be the only subcontractors qualified to construct the FRP requirements and shall comply with this process specification. Any deviations or variations are to be submitted to ERA for approval with proper documentation prior to

fabrication.

Conflicts:

In the event of a conflict with engineering

drawing(s) and this specification, the

drawing(s) shall govern.

Fabrication of the Engine Air Inlet for

the C 20 R Engine for the BO-105

Rev '	   Date 	Pages	Approvals   Manufacturing   Quality Control   MESH   ERA   MESH   ERA			trol   Engineering ERA   MESH   ERA		
IR.	1/18/88	All	Aud	LH.	187	Gn	BZ	LERA VIEW
	1-1		    -					
	•.							-
							•	
			, .					

PAGE 1 of 17

ERA PS -ERA-1024

1/18/88

ERA PS 1024 REV TR DATE 1/18/88

MATERIALS

MANUFACTURER NAME MATERIALS Dow Chemical Derakane 8084 Resin Midland, MI AKZO Chemie Cobalt Napthenate Promoter New Brunswick, NJ Buffalo Colors Dimethylaniline Accelerator West Paterson, NJ Witco Chemical Hi Point 90 MEKP Catalyst Richmond, CA Lucidol Chemical Lupersol DHD 9 Buffalo, NY Rexco PVA Mold Release Carpentería, CA Cerea Mold Release Wax Ceara Products, Inc. Denver, CO Industrial Chemicals UV-9 UV Inhibitor Atlanta, GA CoPlas CoPlas pigment Pigment Fort Smith, AR Spartan Pigments Spartan pigment Houston, TX CoPlas Inc. Gel Coat Gel Coat Ft. Smith, Ark.

<b>DATE</b> 6/26/95	ENGINEEF	RING ORE	DER	<b>E.O. No.</b> A−1	SHT. _1_of_1
BY · T. Harville	PROCESS S	TLE SPECIFIC	ATION	<b>DWG. AFI</b>	4
APPROVED BY	-	JI LOH IO/	-711O14	ENTERED ON (	
REASON FOR CHANGE: A	DD ALT P/N FO SLASS MAT (M12		1/2 0	z TYPE "	7 5 Number
3/4 oz TYPE "E"	GLASS MAT.	M113-3/4 OR M127-3/4	oz CE	CHITA FAI	LS, TX D
1 1/2 oz TYPE '	'E'' GLASS MAT.	M113-1 OR M127-1	WI 1/2 02	CHITA FAI	LLS, TX nteed

# MATERIALS

MATERIALS .	NAME	MANUFACTURER
3/4 oz Type 'E' glass mat	M113 - 3/4 oz.	Certainteed Wichita Falls, TX
1-1/2 oz Type 'E' glass mat	Compatamat - 1-1/2 oz.	PPG Industries Shelby, NC
	M113 - 1-1/2  oz.	Certainteed Wichita Falls, TX
8.9 oz. Type "ECDE" glass	7781	Burlington Fibers Altavista, VA
10 mil °C' glass, or	Modiglass	Reichold Chemical Bremen, OH
	Manville Glass	Manville Corp. Denver, CO
10 mil 'A' glass veil	Surglass	Superior Glass Bremen, OH
Fire Retardant Additive	Nyacol APE-1540	PQ Corp. Ashland, Ma.
Fire Retardant Additive	Decabromodiphenyl Oxide	Ethyl Corp. Magnolia, Ark.

PAGE 3 of 17

ERA PS 1024 REV IR DATE 1/18/88

MATERIALS

MATERIALS

NAME

MANUFACTURER

Grinding Discs

36 Grit Type D

60 Grit Type C

St. Paul, MN

80 Grit Type C

Mold Surface

Black Tooling Gel

Glidden

PAGE 4 of 17

ERA	PS	1024	REV	IR	DATE_	1/18/88

# Laminate Manufacture - Part A

- Inspect mold for defects (ie. chips, cracks, crazing, etc. ...).
   DO Not proceed until any defect is corrected.
- 2) Apply mold release agent(s) according to manufacturer's instructions.
- 3) Apply gel-coat containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, pigment and UV inhibitor onto mold using a spray gun for a nominal thickness of 10 mils, minimum thickness of 6 mils.
- 4) Allow gel-coat to cure for 4 6 hours and become tack free.
- 5) Apply one layer of 3/4 oz. chopped strand mat on mold surfaces. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
- 6) Apply one layer of ECDE glass cloth. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540. UV inhibitor and pigment. Deaerate with serrated rollers.
- 7) Apply 2nd layer of 3/4 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
- 8) Apply 2nd layer of ECDE glass cloth. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
- 9) Apply 3rd layer of 3/4 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
- 10) Allow to cure for 4 6 hours. Separate from mold and trim to size.

PAGE 5 of 17

ERA	PS	1024	REV	IR		DATE	1/18/88	
	•							
		Laminate Manu on flat mold		- Part B	- Flat	stock	made	

- Inspect mold for defects (ie. chips, cracks, crazing, etc. ...).
   DO Not proceed until any defect is corrected.
- 2) Apply mold release agent(s) according to manufacturer's instructions.
- 3) Apply one layer of 1 1/2 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
- 4) Apply 2nd layer of 1 1/2 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
- 5) Apply 3rd layer of 1 1/2 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
- 6) Apply 4th layer of 1 1/2 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
- 7) Apply 5th layer of 1 1/2 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
- 8) Apply 6th layer of 1 1/2 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
- 9) Allow to exotherm and cool.
- 10) Apply 7th layer of 1 1/2 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.

Page 6 of 17

	Laminate Manufacture - Part B - Cont.
11)	Apply 8th layer of 1 1/2 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
12)	Apply 9th layer of 1 1/2 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
13)	Apply 10th layer of 1 1/2 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
14)	Apply 11th layer of 1 1/2 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
15)	Apply 12th layer of 1 1/2 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
16)	Separate from mold and trim to size.
	Laminate Manufacture - Part C
1)	Inspect mold for defects (ie. chips, cracks, crazing, etc).  DO Not proceed until any defect is corrected.
2)	Apply mold release agent(s) according to manufacturer's instructions.
3)	Apply one layer of 3/4 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrate rollers.
4)	Allow to cure 4 - 6 hours. Separate from mold and trim to size.
	Laminate Manufacture - Part D
1)	Using flat stock form Part B cut out 2 pieces using the master pattern.
2)	Sand each piece using 40 grit sandpaper.

ERA PROCESS SPECIFICATION

REV

1/18/88

Page 7 of 17

E	RAPS 1024 REV IR DATE 1/18/88
	Laminate Manufacture - Part D - Cont.
3)	Apply one layer of 3/4 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrate rollers.
4)	While the mat is wet clamp the pieces together. Allow to harden and trim to size.
	Assembly of Part
1)	Confirm that Part B is trimmed properly by fitting into position.
2)	Sand inside of Part A where bonding will occur with 40 grit sandpaper.
3)	Apply one layer of 3/4 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrate rollers.
4)	Position part B in Part A while mat is still wet. Allow to harden.
5)	Dress down any rough areas using 40 grit sandpaper.
6)	Confirm that Part C is trimmed properly by positioning in Part A.
7)	Once proper fit has been achieved apply one 3/4 oz. chopped strand mat tying Part C to Part A and Part B. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
8)	Apply 2nd layer of 3/4 oz. chopped strand mat. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrate rollers.
9)	Allow to harden and dress down any rough areas.
	PAGE 8 of 17

ERA PROCESS SPECIFICATION

ERA	PS	1024	REV_	ÎR	DATE	1/18/88
-----	----	------	------	----	------	---------

# Assembly of Part - Cont.

- 10) Fit Part D in Part A as shown on Drawing #10572-101-001 to confirm proper fit.
- 11) Apply one 3/4 oz. chopped strand mat in position where Part D fits into Part A. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
- 12) While mat is still wet, fit part D into place and allow to harden.
- 13) Apply one 1 1/2 oz. chopped strand mat to both sides. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
- 14) Apply 2nd 1 1/2 oz. chopped strand mat to both sides. Saturate with Derakane 8084 resin containing 12% by weight Decabromodiphenyl Oxide, 7.5% by weight Nyacol APE 1540, UV inhibitor and pigment. Deaerate with serrated rollers.
- 15) Allow to cure for 4 6 hours. Dress down any areas of roughness.
- 16) Machine surfaces in accordance with Drawing #10572-101-001.
- 17) Install threaded inserts in accordance with Process Specification 1023.

Page 9 of 17

E	R	Α	P	S	1024

### INSPECTTON

It is the purpose of the inspection to verity that each part has been tabricated in accordance with and meets the requirements of this specification.

RESPONSIBILITIES: It is the responsibility of the fabricator to make

available to ERA Helicopter or its authorized representative any or all of the following:

Records pertaining to the part(s) being purchased Records:

shall be supplied when requested. These may include:

Materials specifications Equipment drawings or mold jig

Materials test results.

Dimensional verification reports.

Rework and repair reports.

#### MATERIALS:

Raw materials used for laminates shall be virgin materials and shall be free of contaminates as described on pgs. 14, 15, 16, and 17.

FABRICATED PARTS:

The part to be inspected shall be properly located and positioned, and shall be in condition to permit sate and thorough inspection. Reasonable means shall be provided to permit the inspector to visually examine the entire inner and outer surfaces of the part.

Allowable defects are listed on pgs. 12 and 13.

The following inspection tools and equipment shall be made available for use by the inspector.

> Barcol hardness tester. Acetone squeeze bottle with acetone. Extension cord with ground fault switch. A vapor tight inspection light. Thickness gauge.

> > PAGE 10 of 17

ERA	PS	1024	REV	IR	DATE	1/18/88
-----	----	------	-----	----	------	---------

#### INSPECTION

TEST OF FINISHED PARTS:

The following basic tests shall be included as a minimum in the Acceptance Inspection.

Barcol Hardness Test - A test of resin cure shall be made in accordance with ASTM D2583. Take 10 readings, discard highest and lowest, average the remaining readings. Minimum acceptable average reading is 30.

Surface Cure Test - An acetone test shall be used to detect surface inhibition on the surfaces exposed to air during cure. The procedure that shall be used is the following: rub a few drops of acetone on the surface and check for tackiness after the acetone has evaporated. Persistent tackiness indicates incomplete cure.

Dimensions - The inspector shall be provided with copies of all approved drawings or mold jigs.

## OTHER APPLICABLE DOCUMENTS:

ASTM Standards

- C 581-74-Test Method for Chemical Resistance of Thermosetting Resins Used in Glass Fiber Reinforced Structures.
- D 638-77a-Test Method for Tensile Properties of Plastics.
- D 790-71-Test Methods for Flexural Properties of Plastics and Electrical Insulating Materials.
- D 883-78a-Definitions of Terms Relating to Plastics.
- D 2583-75-Test Method for Identation Hardness of Rigid Plastics by Means of a Barcol Impressor.

PAGE 11 of 17

ERA	P S	1024	REV_	IR	DATE	1/18/88
-----	-----	------	------	----	------	---------

ALLÓWABLE	DEFECTS
	Surface inspected
Defect	
Cracks(through part)  Crazing (fine surface cracks)	None  Max dimension 1/2 in., max density 5 per sq. tt. min 2 in apart
Blisters(rounded elevations of the laminate surface over bubbles)	Max 1/4 in., dia x 1/8 in high, max 1 per sq ft, min 2 in apart
Wrinkles and solid blisters	Max deviation, 20% of wall thickness but not exceeding 1/8 in.
Pit(craters in the laminate surface)	Max dimensions, $1/8$ in dia x $1/16$ in deep, max density 10 per sq. ft.
Surface porosity(pin- holes or pores in the laminate) 10 per sq. ft.	Max dimensions, $1/16$ in dia. $\times$ $1/16$ in deep, max density
Chips	Max dimensions of break, 1/4 in, and thickness no greater than 20 percent of wall thickness, max density 1 per sq ft
Dry spot(nonwetted reinforcing)	Max dimension, 2 sq in. per sq ft
Entrapped air (bubbles or voids in the laminate)	1/8 in. max dia, 4 per sq in. max density; 1/16 in. max dia. 10 per sq in. max density.

PAGE 12 of 17

ERA PS 1024	REVI	DATE
	ALLOWABLE DEFE	CTS
general control contro	Surfa	ace inspected
Defect Exposed Glass	and the second s	None
Burned Areas		None
Exposure of cut edges		None
Scratches		Max length 1 in. max depth 0.010 in.
Foreign Matter		1/16 in. dia., max density 1 per sq ft

ERA	P S	1024	REV	IR	D A	ATE	1/18/88
-----	-----	------	-----	----	-----	-----	---------

#### FIBERGLASS CHOPPED STRAND MAT

# 1.0 Scope

1.1 The scope of these procedures is to describe the visual, physical and mechanical parameters which characterize fiberglass chopped strand mat used by the fabricator.

# 2.0 Definitions

2.1 Chopped Strand Mat - Chopped strand mat is made from randomly oriented glass strands which are held together in mat form using a binder. Each strand contains a sizing.

## 3.0 Requirements

- 3.1 Visual Requirements Each roll of chopped strand mat shall be inspected to insure it is consistent in color, texture and appearance. It shall be free from surface irregularities, fluffy masses, dirt spots or other foreign material; water spots, knots, binder spots larger than 2" in diameter, clumps of strands and tears of holes which may result from removal of defects.
- 3.2 Physical Requirements
- 3.2.1 Weight The square foot weight of the mat shall be measured for each carton of mat used. All specimens shall fall within the range specified for the product.
- 3.3 Packaging Requirement Packaging shall be visually inspected to assure proper labeling and that the package is free from damage that may render the mat unusable.
- 3.3.1 The mat shall be packaged in an unbroken carton as shipped from the mat manufacturer's factory. The mat used shall not be repackaged in the distribution of the mat after the manufacturer has shipped the mat.

PAGE 14 of 17

8 ERA	PS	1024	REV_	IR	. D	ATE	1/18/88
-------	----	------	------	----	-----	-----	---------

# FIBERGLASS CHOPPED STRAND MAT

- 3.4 Documentation It is the responsibility of the fabricator to maintain records showing the results of all material testing. This information shall show at a minimum, the following:
- (a) Form of material
- (b) Manutacturer
- (c) Manufacturer's product description including binder type (treatment)
- (d) Manufacturer's product code
- (e) Production date, if available, or production code on carton
- (f) Property measured and value recorded
  - \* Visual inspection
  - \* Width
  - \* Thickness
  - \* Packaging
- (g) Job number (Internal Fabricator Control Number)
- (h) Fabricated part identification number

PAGE 15 of 17

ERA	PS	1024	REV_	IR	D	A	T	E	1/18/88	
-----	----	------	------	----	---	---	---	---	---------	--

#### FIBERGLASS WOVEN ROVING

### 1.0 Scope

- 1.1 The scope of these procedures is to describe the visual, physical and mechanical parameters which characterize woven roving used by the fabricator.
- 2.0 Definitions
- 2.1 Fiberglass Woven Roving Glass fiber rovings woven into a heavy weight fabric.
- 2.2 Wrap Ends The rovings which run in the longitudinal direction of the fabric, i.e., along the roll length of the fabric.
- 2.3 Fill Picks The rovings which run in the transverse direction of the fabric, i.e., across the roll length of the fabric.
- 2.4 Leno Strands A pair of warp ends at each edge of the woven fabric. One Leno warp end is always over each fill pick while the other Leno warp end is always under the fill pick. The Leno strands define the edges of the woven field and serve to stabilize the edges of the fabric.
- 3.0 Requirements
- 3.1 Visual Requirements
- 3.1.1 Dirt Spots Defined as all foreign matter, dirt, grease spots, etc. The average number of dirt spots (1/16" to 3/4" in diameter) per 100 lineal feet shall be 6 or less. All rolls shall be free of dirt spots in excess of 3/4" diameter.
- 3.1.2 Warp Ends All rolls shall be free of missing warp ends for more than two consecutive feet.
- 3.1.3 Fill Picks All rolls shall be free of consecutive missing picks in excess of five, or more than eleven missing picks, either individual picks or any combination of individual and multiple (2, 3, 4, or 5) picks, in any consecutive 100 lineal feet.
- 3.1.4 Fuzz Clumps and Loops The product is designed to exhibit proper laydown and shall be free of fuzz clumps or loops exceeding one inch in height from the surface.

PAGE 16 of 17

ERA	PS	1024	REV	IR	DATE	1/18/88
Part 0.9 % #		The second secon				

#### FIBERGLASS WOVEN ROVING

- 3.2 Physical Properties
- 3.2.1 Thickness The thickness of the mat in each roll of woven roving shall be measured.
- 3.3 Packaging Requirement Packaging shall be visually inspected to assure proper labeling and that the package is free from damage that may render the woven roving unusable.
- 3.3.1 The woven roving shall be packaged in an unbroken carton as shipped from the manufacturer's factory. The woven roving used shall not be repackaged in the distribution of the woven roving after the manufacturer has shipped the woven roving.
- 3.4 Documentation It is the responsibility of the fabricator to maintain records showing the results of all material testing. This information shall show at a minimum, the following:
- (a) Form of material
- (b) Manufacturer
- (c) Manufacturer's product description including binder type (treatment)
- (d) Manufacturer's product code
- (e) Production date, if available, or production code on carton.
- (f) Property measured and value recorded
  - \* Visual inspection
  - \* Width
  - \* Thickness
  - \* Packaging
- (g) Job number (Internal Fabricator Control Number)
- (h) Fabricated part identification number

PAGE 17 of 17